

## Zero output of grid-connected inverter

The reactive power can't be zero if the tuning of the P.I controllers is missing and also there may be some inductive components which may lead to a small value of  $Q$  rather than absolute "0";...

